



JV «ARTIKUL AZIYA KABEL»  
Uzbekistan, Chekhov str. 40



Pricelist

14.02.2017 r.

**Power cables**

*with aluminum conductors in PVC insulation*

under 0,66 kV		under 1,0 kV	
ABBF 1x2,5	call	ABBF 1x2,5	call
ABBF 1x4,0	call	ABBF 1x4,0	call
ABBF 1x6,0	call	ABBF 1x6,0	call
ABBF 1x10,0	call	ABBF 1x10,0	call
ABBF 1x16,0	call	ABBF 1x16,0	call
ABBF 1x25,0	call	ABBF 1x25,0	call
ABBF 1x35,0	call	ABBF 1x35,0	call
ABBF 2x2,5	call	ABBF 2x2,5	call
ABBF 2x4,0	call	ABBF 2x4,0	call
ABBF 2x6,0	call	ABBF 2x6,0	call
ABBF 2x10,0	call	ABBF 2x10,0	call
ABBF 2x16,0	call	ABBF 2x16,0	call
ABBF 2x25,0	call	ABBF 2x25,0	call
ABBF 2x35,0	call	ABBF 2x35,0	call
ABBF 3x2,5	call	ABBF 3x2,5	call
ABBF 3x4,0	call	ABBF 3x4,0	call
ABBF 3x6,0	call	ABBF 3x6,0	call
ABBF 3x10,0	call	ABBF 3x10,0	call
ABBF 3x16,0	call	ABBF 3x16,0	call
ABBF 3x25,0	call	ABBF 3x25,0	call
ABBF 3x35,0	call	ABBF 3x35,0	call
ABBF 5x2,5	call	ABBF 5x2,5	call
ABBF 5x4,0	call	ABBF 5x4,0	call
ABBF 5x6,0	call	ABBF 5x6,0	call
ABBF 5x10,0	call	ABBF 5x10,0	call
ABBF 5x16,0	call	ABBF 5x16,0	call
ABBF 5x25,0	call	ABBF 5x25,0	call
ABBF 5x35,0	call	ABBF 5x35,0	call
ABBF 3x4,0+1x2,5	call	ABBF 3x4,0+1x2,5	call
ABBF 3x6,0+1x4,0	call	ABBF 3x6,0+1x4,0	call
ABBF 3x10,0+1x6,0	call	ABBF 3x10,0+1x6,0	call
ABBF 3x16,0+1x10,0	call	ABBF 3x16,0+1x10,0	call
ABBF 3x25+1x16,0	call	ABBF 3x25+1x16,0	call
ABBF 3x35+1x16,0	call	ABBF 3x35+1x16,0	call
ABBF 4x2,5	call	ABBF 4x2,5	call
ABBF 4x4,0	call	ABBF 4x4,0	call
ABBF 4x6,0	call	ABBF 4x6,0	call
ABBF 4x10,0	call	ABBF 4x10,0	call
ABBF 4x16,0	call	ABBF 4x16,0	call
ABBF 4x25	call	ABBF 4x25	call
ABBF 4x35	call	ABBF 4x35	call
<i>with aluminum conductors in PVC insulation for voltage up to 1 kV</i>			
ABBF 1x50	call	ABBF 4x120	call
ABBF 1x70	call	ABBF 4x150	call
ABBF 1x95	call	ABBF 4x185	call
ABBF 1x120	call	ABBF 4x240	call
ABBF 1x150	call	ABBF 5x50	call
ABBF 1x185	call	ABBF 5x70	call
ABBF 1x240	call	ABBF 5x95	call
ABBF 2x50	call	ABBF 5x120	call
ABBF 2x70	call	ABBF 5x150	call
ABBF 2x95	call	ABBF 5x185	call
ABBF 2x120	call	ABBF 5x240	call
ABBF 2x150	call	ABBF 3x50+1x16	call
ABBF 2x185	call	ABBF 3x50+1x25	call
ABBF 2x240	call	ABBF 3x70+1x25	call
ABBF 3x50	call	ABBF 3x70+1x35	call
ABBF 3x70	call	ABBF 3x95+1x35	call
ABBF 3x95	call	ABBF 3x95+1x50	call
ABBF 3x120	call	ABBF 3x120+1x35	call
ABBF 3x150	call	ABBF 3x120+1x70	call
ABBF 3x185	call	ABBF 3x150+1x50	call
ABBF 3x240	call	ABBF 3x150+1x70	call
ABBF 4x50	call	ABBF 3x185+1x50	call
ABBF 4x70	call	ABBF 3x185+1x95	call
ABBF 4x95	call	ABBF 3x240+1x70	call
	call	ABBF 3x240+1x120	call
under 0,66 kV		under 1,0 kV	
ABBF-II 2x2,5	call	ABBF-II 2x2,5	call
ABBF-II 2x4,0	call	ABBF-II 2x4,0	call
ABBF-II 2x6,0	call	ABBF-II 2x6,0	call
ABBF-II 2x10,0	call	ABBF-II 2x10,0	call
ABBF-II 2x16,0	call	ABBF-II 2x16,0	call
ABBF-II 3x2,5	call	ABBF-II 3x2,5	call
ABBF-II 3x4,0	call	ABBF-II 3x4,0	call

ABBГ-II 3x6,0	call	ABBГ-II 3x6,0	call
ABBГ-II 3x10	call	ABBГ-II 3x10	call
<b>with aluminum conductors, insulated with non-flammable PVC</b>			
under 0,66 kV		under 1,0 kV	
ABBГ нг 1x2,5	call	ABBГ нг 1x2,5	call
ABBГ нг 1x4,0	call	ABBГ нг 1x4,0	call
ABBГ нг 1x6,0	call	ABBГ нг 1x6,0	call
ABBГ нг 1x10,0	call	ABBГ нг 1x10,0	call
ABBГ нг 1x16,0	call	ABBГ нг 1x16,0	call
ABBГ нг 1x25,0	call	ABBГ нг 1x25,0	call
ABBГ нг 1x35,0	call	ABBГ нг 1x35,0	call
ABBГ нг 2x2,5	call	ABBГ нг 1x50,0	call
ABBГ нг 2x4,0	call	ABBГ нг 1x70,0	call
ABBГ нг 2x6,0	call	ABBГ нг 1x95	call
ABBГ нг 2x10,0	call	ABBГ нг 1x120	call
ABBГ нг 2x16,0	call	ABBГ нг 1x150	call
ABBГ нг 2x25,0	call	ABBГ нг 1x185	call
ABBГ нг 2x35,0	call	ABBГ нг 1x240	call
ABBГ нг 3x2,5	call	ABBГ нг 2x2,5	call
ABBГ нг 3x4,0	call	ABBГ нг 2x4,0	call
ABBГ нг 3x6,0	call	ABBГ нг 2x6,0	call
ABBГ нг 3x10,0	call	ABBГ нг 2x10,0	call
ABBГ нг 3x16,0	call	ABBГ нг 2x16,0	call
ABBГ нг 3x25,0	call	ABBГ нг 2x25,0	call
ABBГ нг 3x35,0	call	ABBГ нг 2x35,0	call
ABBГ нг 5x2,5	call	ABBГ нг 3x2,5	call
ABBГ нг 5x4,0	call	ABBГ нг 3x4,0	call
ABBГ нг 5x6,0	call	ABBГ нг 3x6,0	call
ABBГ нг 5x10,0	call	ABBГ нг 3x10,0	call
ABBГ нг 5x16,0	call	ABBГ нг 3x16,0	call
ABBГ нг 5x25,0	call	ABBГ нг 3x25,0	call
ABBГ нг 5x35,0	call	ABBГ нг 3x35,0	call
ABBГ нг 3x4,0+1x2,5	call	ABBГ нг 5x2,5	call
ABBГ нг 3x6,0+1x4,0	call	ABBГ нг 5x4,0	call
ABBГ нг 3x10,0+1x6,0	call	ABBГ нг 5x6,0	call
ABBГ нг 3x16,0+1x10,0	call	ABBГ нг 5x10,0	call
ABBГ нг 3x25+1x16,0	call	ABBГ нг 5x16,0	call
ABBГ нг 3x35+1x16,0	call	ABBГ нг 5x25,0	call
ABBГ нг 4x2,5	call	ABBГ нг 5x35,0	call
ABBГ нг 4x4,0	call	ABBГ нг 3x4,0+1x2,5	call
ABBГ нг 4x6,0	call	ABBГ нг 3x6,0+1x4,0	call
ABBГ нг 4x10,0	call	ABBГ нг 3x10,0+1x6,0	call
ABBГ нг 4x16,0	call	ABBГ нг 3x16,0+1x10,0	call
ABBГ нг 4x25	call	ABBГ нг 3x25+1x16,0	call
ABBГ нг 4x35	call	ABBГ нг 3x35+1x16,0	call
		ABBГ нг 4x2,5	call
		ABBГ нг 4x4,0	call
		ABBГ нг 4x6,0	call
		ABBГ нг 4x10,0	call
		ABBГ нг 4x16,0	call
		ABBГ нг 4x25	call
		ABBГ нг 4x35	call
<b>with aluminum conductors, PVC insulated, steel</b>			
under 0,66 kV		under 1,0 kV	
ABБ6Шв 1x2,5	call	ABБ6Шв 1x2,5	call
ABБ6Шв 1x4,0	call	ABБ6Шв 1x4,0	call
ABБ6Шв 1x6,0	call	ABБ6Шв 1x6,0	call
ABБ6Шв 1x10,0	call	ABБ6Шв 1x10,0	call
ABБ6Шв 1x16,0	call	ABБ6Шв 1x16,0	call
ABБ6Шв 1x25,0	call	ABБ6Шв 1x25,0	call
ABБ6Шв 1x35,0	call	ABБ6Шв 1x35,0	call
ABБ6Шв 2x2,5	call	ABБ6Шв 1x50	call
ABБ6Шв 2x4,0	call	ABБ6Шв 1x70	call
ABБ6Шв 2x6,0	call	ABБ6Шв 1x95	call
ABБ6Шв 2x10,0	call	ABБ6Шв 1x120	call
ABБ6Шв 2x16,0	call	ABБ6Шв 1x150	call
ABБ6Шв 2x25,0	call	ABБ6Шв 1x185	call
ABБ6Шв 2x35,0	call	ABБ6Шв 1x240	call
ABБ6Шв 3x2,5	call	ABБ6Шв 2x2,5	call
ABБ6Шв 3x4,0	call	ABБ6Шв 2x4,0	call
ABБ6Шв 3x6,0	call	ABБ6Шв 2x6,0	call
ABБ6Шв 3x10,0	call	ABБ6Шв 2x10,0	call
ABБ6Шв 3x16,0	call	ABБ6Шв 2x16,0	call
ABБ6Шв 3x25,0	call	ABБ6Шв 2x25,0	call
ABБ6Шв 3x35,0	call	ABБ6Шв 2x35,0	call
ABБ6Шв 3x4,0+1x2,5	call	ABБ6Шв 2x50	call
ABБ6Шв 3x6,0+1x4,0	call	ABБ6Шв 2x70	call
ABБ6Шв 3x10,0+1x6,0	call	ABБ6Шв 2x95	call
ABБ6Шв 3x16,0+1x10,0	call	ABБ6Шв 2x120	call
ABБ6Шв 3x25+1x16,0	call	ABБ6Шв 2x150	call
ABБ6Шв 3x35+1x16,0	call	ABБ6Шв 2x185	call
ABБ6Шв 4x2,5	call	ABБ6Шв 2x240	call
ABБ6Шв 4x4,0	call	ABБ6Шв 3x2,5	call
ABБ6Шв 4x6,0	call	ABБ6Шв 3x4,0	call
ABБ6Шв 4x10,0	call	ABБ6Шв 3x6,0	call
ABБ6Шв 4x16,0	call	ABБ6Шв 3x10,0	call
ABБ6Шв 4x25	call	ABБ6Шв 3x16,0	call
ABБ6Шв 4x35	call	ABБ6Шв 3x25,0	call
ABБ6Шв 5x2,5	call	ABБ6Шв 3x35,0	call



BBГ 4x16,0	call	BBГ 2x240	call	BBГ 3x6,0+1x4,0	call
BBГ 4x25,0	call	BBГ 3x1,5	call	BBГ 3x10,0+1x6,0	call
BBГ 4x35,0	call	BBГ 3x2,5	call	BBГ 3x16,0+1x10,0	call
BBГ 5x1,5	call	BBГ 3x4,0	call	BBГ 3x25+1x16,0	call
BBГ 5x2,5	call	BBГ 3x6,0	call	BBГ 3x35+1x16,0	call
BBГ 5x4,0	call	BBГ 3x10,0	call	BBГ 3x50+1x16	call
BBГ 5x6,0	call	BBГ 3x16,0	call	BBГ 3x50+1x25	call
BBГ 5x10,0	call	BBГ 3x25,0	call	BBГ 3x70+1x25	call
BBГ 5x16,0	call	BBГ 3x35,0	call	BBГ 3x70+1x35	call
BBГ 5x25,0	call	BBГ 3x50,0	call	BBГ 3x95+1x35	call
BBГ 5x35,0	call	BBГ 3x70,0	call	BBГ 3x95+1x50	call
BBГ 3x1,5+1x1,0	call	BBГ 3x95,0	call	BBГ 3x120+1x35	call
BBГ 3x2,5+1x1,5	call	BBГ 3x120,0	call	BBГ 3x120+1x70	call
BBГ 3x4,0+1x2,5	call	BBГ 3x150,0	call	BBГ 3x150+1x50	call
BBГ 3x6,0+1x4,0	call	BBГ 3x185,0	call	BBГ 3x150+1x70	call
BBГ 3x10,0+1x6,0	call	BBГ 3x240,0	call	BBГ 3x185+1x50	call
BBГ 3x16+1x10,0	call	BBГ 4x1,5	call	BBГ 3x185+1x95	call
BBГ 3x25+1x16,0	call	BBГ 4x2,5	call	BBГ 3x240+1x70,0	call
BBГ 3x35+1x16,0	call	BBГ 4x4,0	call	BBГ 3x240+1x120,0	call

*with copper conductors insulated with non-flammable PVC*

under 0,66 kV		under 1,0 kV	
BBГ нг 1x1,5	call	BBГ нг 1x1,5	call
BBГ нг 1x2,5	call	BBГ нг 1x2,5	call
BBГ нг 1x4,0	call	BBГ нг 1x4,0	call
BBГ нг 1x6,0	call	BBГ нг 1x6,0	call
BBГ нг 1x10,0	call	BBГ нг 1x10,0	call
BBГ нг 1x16,0	call	BBГ нг 1x16,0	call
BBГ нг 1x25,0	call	BBГ нг 1x25,0	call
BBГ нг 1x35,0	call	BBГ нг 1x35,0	call
BBГ нг 2x1,5	call	BBГ нг 2x1,5	call
BBГ нг 2x2,5	call	BBГ нг 2x2,5	call
BBГ нг 2x4,0	call	BBГ нг 2x4,0	call
BBГ нг 2x6,0	call	BBГ нг 2x6,0	call
BBГ нг 2x10,0	call	BBГ нг 2x10,0	call
BBГ нг 2x16,0	call	BBГ нг 2x16,0	call
BBГ нг 2x25,0	call	BBГ нг 2x25,0	call
BBГ нг 2x35,0	call	BBГ нг 2x35,0	call
BBГ нг 3x1,5	call	BBГ нг 3x1,5	call
BBГ нг 3x2,5	call	BBГ нг 3x2,5	call
BBГ нг 3x4,0	call	BBГ нг 3x4,0	call
BBГ нг 3x6,0	call	BBГ нг 3x6,0	call
BBГ нг 3x10,0	call	BBГ нг 3x10,0	call
BBГ нг 3x16,0	call	BBГ нг 3x16,0	call
BBГ нг 3x25,0	call	BBГ нг 3x25,0	call
BBГ нг 3x35,0	call	BBГ нг 3x35,0	call
BBГ нг 3x2,5+1x1,5	call	BBГ нг 3x2,5+1x1,5	call
BBГ нг 3x4,0+1x2,5	call	BBГ нг 3x4,0+1x2,5	call
BBГ нг 3x6,0+1x4,0	call	BBГ нг 3x6,0+1x4,0	call
BBГ нг 3x10,0+1x6,0	call	BBГ нг 3x10,0+1x6,0	call
BBГ нг 3x16,0+1x10,0	call	BBГ нг 3x16,0+1x10,0	call
BBГ нг 3x25+1x16,0	call	BBГ нг 3x25+1x16,0	call
BBГ нг 3x35+1x16,0	call	BBГ нг 3x35+1x16,0	call
BBГ нг 4x2,5	call	BBГ нг 4x2,5	call
BBГ нг 4x4,0	call	BBГ нг 4x4,0	call
BBГ нг 4x6,0	call	BBГ нг 4x6,0	call
BBГ нг 4x10,0	call	BBГ нг 4x10,0	call
BBГ нг 4x16,0	call	BBГ нг 4x16,0	call
BBГ нг 4x25,0	call	BBГ нг 4x25,0	call
BBГ нг 4x35,0	call	BBГ нг 4x35,0	call
BBГ нг 5x1,5	call	BBГ нг 5x1,5	call
BBГ нг 5x2,5	call	BBГ нг 5x2,5	call
BBГ нг 5x4,0	call	BBГ нг 5x4,0	call
BBГ нг 5x6,0	call	BBГ нг 5x6,0	call
BBГ нг 5x10,0	call	BBГ нг 5x10,0	call
BBГ нг 5x16,0	call	BBГ нг 5x16,0	call
BBГ нг 5x25,0	call	BBГ нг 5x25,0	call
BBГ нг 5x35,0	call	BBГ нг 5x35,0	call

under 0,66 kV		under 1,0 kV	
BBГ нг(A)LS 3x2,5+1x1,5	call	BBГ нг(A)LS 3x2,5+1x1,5	call
BBГ нг(A)LS 3x4,0+1x2,5	call	BBГ нг(A)LS 3x4,0+1x2,5	call
BBГ нг(A)LS 3x6,0+1x4,0	call	BBГ нг(A)LS 3x6,0+1x4,0	call
BBГ нг(A)LS 3x10,0+1x6,0	call	BBГ нг(A)LS 3x10,0+1x6,0	call
BBГ нг(A)LS 3x16,0+1x10,0	call	BBГ нг(A)LS 3x16,0+1x10,0	call
BBГ нг(A)LS 3x25+1x16,0	call	BBГ нг(A)LS 3x25+1x16,0	call
BBГ нг(A)LS 3x35+1x16,0	call	BBГ нг(A)LS 3x35+1x16,0	call
BBГ нг(A)LS 4x2,5	call	BBГ нг(A)LS 4x2,5	call
BBГ нг(A)LS 4x4,0	call	BBГ нг(A)LS 4x4,0	call
BBГ нг(A)LS 4x6,0	call	BBГ нг(A)LS 4x6,0	call
BBГ нг(A)LS 4x10,0	call	BBГ нг(A)LS 4x10,0	call
BBГ нг(A)LS 4x16,0	call	BBГ нг(A)LS 4x16,0	call
BBГ нг(A)LS 4x25	call	BBГ нг(A)LS 4x25	call
BBГ нг(A)LS 4x35	call	BBГ нг(A)LS 4x35	call

*with aluminum conductors, PVC insulated, steel*

under 0,66 kV		under 1,0 kV	
BB6Шв 3x2,5+1x1,5	call	BB6Шв 4x2,5	call
BB6Шв 3x4,0+1x2,5	call	BB6Шв 4x4,0	call
BB6Шв 3x6,0+1x4,0	call	BB6Шв 4x6,0	call
BB6Шв 3x10,0+1x6,0	call	BB6Шв 4x10,0	call
BB6Шв 3x16,0+1x10,0	call	BB6Шв 4x16,0	call
BB6Шв 3x25+1x16,0	call	BB6Шв 4x25,0	call
BB6Шв 3x35+1x16,0	call	BB6Шв 4x35,0	call

ВБ6Шв 4x2,5	call	ВБ6Шв 3x2,5+1x1,5	call
ВБ6Шв 4x4,0	call	ВБ6Шв 3x4,0+1x2,5	call
ВБ6Шв 4x6,0	call	ВБ6Шв 3x6,0+1x4,0	call
ВБ6Шв 4x10,0	call	ВБ6Шв 3x10,0+1x6,0	call
ВБ6Шв 4x16,0	call	ВБ6Шв 3x16,0+1x10,0	call
ВБ6Шв 4x25	call	ВБ6Шв 3x25,0+1x16	call
ВБ6Шв 4x35	call	ВБ6Шв 3x35,0+1x16	call
<b>Household wires</b>			
ППВ 2 x 1,0	call	АППБН 2x4	call
ППВ 2 x 1,5	call	АППБН 2x6	call
ППВ 2 x 2,5	call	АППБН 3x2,5	call
ППВ 2 x 4	call	АППБН 3x4	call
ППВ 3 x 1,0	call	АППБН 3x6	call
ППВ 3 x 1,5	call	АППБН 3x10	call
ППВ 3 x 2,5	call	ПУГНП 2x0,50	call
ППВ 3 x 4	call	ПУГНП 2x0,75	call
ППВ 3 x 6	call	ПУГНП 2x1,0	call
ППБН 2x1,5	call	ПУГНП 2x1,5	call
ППБН 2x2,5	call	ПУГНП 2x2,5	call
ППБН 2x4,0	call	ПУГНП 2x4,0	call
ППБН 2x6,0	call	ПУГНП 2x6,0	call
ППБН 3x1,5	call	ПУГНП 3x0,50	call
ППБН 3x2,5	call	ПУГНП 3x0,75	call
ППБН 3x4,0	call	ПУГНП 3x1,0	call
ППБН 3x6,0	call	ПУГНП 3x1,5	call
ПУН 1,5	call	ПУГНП 3x2,5	call
ПУН 2,5	call	ПУГНП 3x4,0	call
ПУН 4,0	call	ПУГНП 3x6,0	call
ПУН 6,0	call	ВВП-1 2x1,5	call
ПУНП 2x1,5	call	ВВП-1 2x2,5	call
ПУНП 2x2,5	call	ВВП-1 2x4,0	call
ПУНП 2x4,0	call	ВВП-1 2x6,0	call
ПУНП 2x6,0	call	ВВП-1 3x1,5	call
ПУНП 3x1,5	call	ВВП-1 3x2,5	call
ПУНП 3x2,5	call	ВВП-1 3x4,0	call
ПУНП 3x4,0	call	ВВП-1 3x6,0	call
ПУНП 3x6,0	call	ВВП-1 2x1,5	call
АПУНП 2x2,5	call	ВВП-1 2x2,5	call
АПУНП 2x4	call	ВВП-1 2x4,0	call
АПУНП 2x6	call	ВВП-1 2x6,0	call
АПУНП 3x2,5	call	ВВП-1 3x1,5	call
АПУНП 3x4	call	ВВП-1 3x2,5	call
АПУНП 3x6	call	ВВП-1 3x4,0	call
АППБН 2x2,5	call	ВВП-1 3x6,0	call
ПВС 2x0,35	call	ПВС 3x0,35	call
ПВС 2x0,50	call	ПВС 3x0,50	call
ПВС 2x0,75	call	ПВС 3x0,75	call
ПВС 2x1,0	call	ПВС 3x1,0	call
ПВС 2x1,5	call	ПВС 3x1,5	call
ПВС 2x2,5	call	ПВС 3x2,5	call
ПВС 2x4,0	call	ПВС 3x4,0	call
ПВС 2x6,0	call	ПВС 3x6,0	call
ПВС 2x10,0	call	ПВС 3x10,0	call
ПВС 2x16,0	call	ПВС 3x16,0	call
ПВС 4x0,35	call	ПВС 5x0,35	call
ПВС 4x0,50	call	ПВС 5x0,50	call
ПВС 4x0,75	call	ПВС 5x0,75	call
ПВС 4x1,0	call	ПВС 5x1,0	call
ПВС 4x1,5	call	ПВС 5x1,5	call
ПВС 4x2,5	call	ПВС 5x2,5	call
ПВС 4x4,0	call	ПВС 5x4,0	call
ПВС 4x6,0	call	ПВС 5x6,0	call
ПВС 4x10,0	call	ПВС 5x10,0	call
ПВС 4x16,0	call	ПВС 5x16,0	call
ШВВП 2x0,50	call	ШВВП 3x0,50	call
ШВВП 2x0,75	call	ШВВП 3x0,75	call
ШВВП 2x1,0	call	ШВВП 3x1,0	call
ШВВП 2x1,5	call	ШВВП 3x1,5	call
ШВВП 2x2,5	call	ШВВП 3x2,5	call
ШВВП 2x4,0	call	ШВВП 3x4,0	call
ШВВП 2x6,0	call	ШВВП 3x6,0	call

MOUNTING WIRES			
<i>with copper wire</i>			
ПВ1 0,75	call	ПВ2 50,0	call
ПВ1 1,0	call	ПВ2 70,0	call
ПВ1 1,5	call	ПВ2 95,0	call
ПВ1 2,5	call	ПВ2 120,0	call
ПВ1 4,0	call	ПВ2 150	call
ПВ1 6,0	call	ПВ2 185	call
ПВ1 10,0	call	ПВ2 240	call
ПВ1 16,0	call	ПВ3 0,75	call
ПВ1 25,0	call	ПВ3 1,0	call
ПВ1 35,0	call	ПВ3 1,5	call
ПВ1 50,0	call	ПВ3 2,5	call
ПВ2 0,75	call	ПВ3 4,0	call
ПВ2 1,0	call	ПВ3 6,0	call
ПВ2 1,5	call	ПВ3 10,0	call
ПВ2 2,5	call	ПВ3 16,0	call
ПВ2 4,0	call	ПВ3 25,0	call
ПВ2 6,0	call	ПВ3 35,0	call
ПВ2 10,0	call	ПВ3 50,0	call
ПВ2 16,0	call	ПВ3 70,0	call
ПВ2 25,0	call	ПВ3 95,0	call
ПВ2 35,0	call	ПВ3 120,0	call
<i>with aluminum core</i>			
АПВ 2,5	call	АПВВ 2x2,5	call
АПВ 4	call	АПВВ 2x4	call
АПВ 6	call	АПВВ 2x6	call
АПВ 10	call	АПВВ 3x2,5	call
АПВ 16	call	АПВВ 3x4	call
АПВ 25	call	АПВВ 3x6	call
АПВ 35	call		
АПВ 50	call	АПВН 1x2,5	call
АПВ 70	call	АПВН 1x4,0	call
АПВ 95	call	АПВН 1x6,0	call
АПВ 120	call	АПВН 1x10,0	call
АПВ 150	call		
АПВ 185	call		
АПВ 240	call		
Control cables			
КВВГ 4x2,5	call	АКВВГ 4x2,5	call
КВВГ 5x2,5	call	АКВВГ 4x4,0	call
КВВГ 7x2,5	call	АКВВГ 4x6,0	call
КВВГ 4x4,0	call	АКВВГ 4x10	call
КВВГ 7x4,0	call	АКВВГ 5x2,5	call
КВВГ 4x6,0	call	АКВВГ 5x4,0	call
КВВГ 7x6,0	call	АКВВГ 5x6,0	call
КВВГ 4x1,5	call	АКВВГ 5x10,0	call
КВВГ 5x1,5	call	АКВВГ 7x2,5	call
КВВГ 7x1,5	call	АКВВГ 7x4,0	call
		АКВВГ 7x6,0	call
		АКВВГ 7x10	call
Winding wires for in water immersion motors			
for 380V			
ППО 1 x 1,60	call	ВПП 1,2	call
ППО 1 x 2,12	call	ВПП 1,5	call
ППО 1 x 2,25	call	ВПП 2,0	call
ППО 1 x 2,50	call	ВПП 2,5	call
ППО 1 x 3,18	call	ВПП 3,0	call
ППО 1 x 3,75	call	ВПП 4,0	call
ППО 1 x 4,50	call	ВПП 5,0	call
ППО 1 x 6,00	call	ВПП 6,0	call
ППО 1 x 8,00	call	ВПП 8,0	call
ППО 1 x 12,5	call	ВПП 10,0	call
ППО 1 x 16,0	call	ВПП 16,0	call
ППО 1 x 20,0	call	ВПП 25,0	call
		ВПП 35,0	call
		ВПП 50,0	call
		ВПП 70,0	call
for 660V			
ВПП 1,2	call	ПВ/ДП 1,4	call
ВПП 1,5	call	ПВ/ДП 1,6	call
ВПП 2,0	call	ПВ/ДП 1,8	call
ВПП 2,5	call	ПВ/ДП 2,0	call
ВПП 3,0	call	ПВ/ДП 2,12	call

ВПП 4,0	call	ПВ/П 2,36	call
ВПП 5,0	call	ПВ/П 2,50	call
ВПП 6,0	call	ПВ/П 2,80	call
ВПП 8,0	call	ПВ/П 3,18	call
ВПП 10,0	call	ПВ/П 3,54	call
ВПП 16,0	call	ПВ/П 3,75	call
ВПП 25,0	call	ПВ/П 3,96	call
ВПП 35,0	call	ПВ/П 4,50	call
ВПП 50,0	call	ПВ/П 4,80	call
ВПП 70,0	call	ПВ/П 5,30	call
		ПВ/П 5,90	call
		ПВ/П 6,25	call
<b>Bare aluminum wire (per 1 ton)</b>			
A 16	call	AC 35,0/6,2	call
A 25	call	AC 50,0/8,0	call
A 35	call	AC 70,0/11,0	call
A 50	call	AC 95,0/16,0	call
A 70	call	AC 120,0/19,0	call
A 95	call	AC 120,0/27,0	call
AC 10,0/1,8	call	AC 150,0/24,0	call
AC 16,0/2,7	call	AC 185,0/29,0	call
AC 25,0/4,2	call	AC 240,0/39,0	call
		AC 240,0/56,0	call
<b>Self-supporting insulated wire (SIW)</b>			
for 0,66/1kV			
СИП-1 1x16+1x25	call	СИП-2 3x16+1x25	call
СИП-1 3x16+1x25	call	СИП-2 3x16+1x54,6	call
СИП-1 3x25+1x35	call	СИП-2 3x25+1x35	call
СИП-1 3x35+1x50	call	СИП-2 3x25+1x54,6	call
СИП-1 3x50+1x50	call	СИП-2 3x35+1x50	call
СИП-1 3x50+1x54,6	call	СИП-2 3x35+1x54,6	call
СИП-1 3x50+1x70	call	СИП-2 3x50+1x50	call
СИП-1 3x70+1x70	call	СИП-2 3x50+1x54,6	call
СИП-1 3x70+1x95	call	СИП-2 3x50+1x70	call
СИП-1 3x95+1x70	call	СИП-2 3x70+1x54,6	call
СИП-1 3x95+1x95	call	СИП-2 3x70+1x70	call
СИП-1 3x120+1x95	call	СИП-2 3x70+1x95	call
СИП-1 3x150+1x95	call	СИП-2 3x95+1x70	call
СИП-1 3x185+1x95	call	СИП-2 3x95+1x95	call
СИП-1 3x240+1x95	call	СИП-2 3x120+1x95	call
		СИП-2 3x150+1x95	call
		СИП-2 3x185+1x95	call
		СИП-2 3x240+1x95	call
for 0,66/1kV			
СИП-4 2x16	call	СИП-4 4x50	call
СИП-4 4x16	call	СИП-4 2x70	call
СИП-4 2x25	call	СИП-4 4x70	call
СИП-4 4x25	call	СИП-4 2x95	call
СИП-4 2x35	call	СИП-4 4x95	call
СИП-4 4x35	call	СИП-4 2x120	call
СИП-4 2x50	call	СИП-4 4x120	call
Fax: (+998 71) 257-41-81 www.artikul-kabel.uz		Phone: (+998 71) 257-82-68, 257-43-44 E-mail: aak.marketing@yandex.ru	

1